


GROUP 3 REPORT AREA SEVEN RFI SITE AREAS



Photos
UNDER ELV.
Piston ELV
POND ELV

— TCE - TANK ACFA —

Dry wall Bravo.

HW SA

SPA - into Area III

Bravo

REI - REI map. should be in Vol. I

MAPS? How can a Normal person know what they are looking at
The only maps are of The Ecological Surveys?
Not community friendly

Building Feature Documentation log.
does not include all drains & sinks.
This is incomplete.

NFA should not be a word in any of the REI's

You take video of AIFA & water

EPA Historical photos

Photo from Power Point
TCE → Bm sediments

Page 31 of 35 of OPT
Need HAZAR map

HAZAROUS waste coolant tank
NFA

5/1/88
5/1/88
5/1/88



IA. The Group 3 Remedial Investigation Report, Ventura County, California, Volume 1

The very first page with the Engineer
certification signatures is missing the
information of which company prepared the
Report. Example. Group 2 similar Books, and is NASA
reads prepared on the left of NASA
and prepared by CH2M HILL. Group 3 does not
indicate this. This could pose a problem as people
~~who~~ need to know who prepared these maps as
there has been a lot of distrust in the count
as far as which of the RPI Contractors are
doing a better job or not.

The other issue I have with this Group
is the fact there are only 3 volumes when the
other RPI RFI areas have several. The Group 3
RFI area is one of the most important as far
as TCE contamination goes as it holds
the bulk of the test studs that were in
operation up until ~~mid~~ 2006 with the last
test at the AIFA test studs.

Ormy Dodge - TCE

Worner Health Study - TCE

775? For Photos by Dr. Fisher

I have photos

AREA 2

AREA 3

ZONE	NO.	TITLE	ZONE	NO.	TITLE
B9	201	S.S. ENGINEERING BLDG	G27	210	STL-4 LUNCH/SMOKE ROOM
B9	202	MAINTENANCE STOCK ROOM	G27	221	STL-4 ENGINEERING OFFICE
B20	203	S.S. SERVICE BLDG	G21	251	RANCH HOUSE STORAGE
B25	204	S.S. MAINTENANCE BLDG	G21	252	RANCH HOUSE FORMING STORES & MACHINE SHOP
B25	205	MAINTENANCE LUNCH ROOM	G27	253	STL-4 MODULE #1
B2	206	STORAGE (CTL-21)	G27	254	STL-4 RECORDING CENTER
B26	207	PROTECTIVE SERVICES BLDG	G28	255	STL-4 MODULE #3
B38	208	ALFA RECORDING CENTER	G27	256	STL-4 WORKSHOP
B37	209	ALFA TERMINAL BLDG	G27	257	STL-4 INSPECTION OFFICE
B9	211	ENGINEERING OFFICES	H8	258	CWLL OFFICE
B38	212	ALFA PRETEST BLDG	H8	259	CHEMICAL STORAGE BLDG
B4	213	BRAVO RECORDING CENTER	H8	260	ECL CHEMICAL & INSTRUMENT STORAGE
B4	214	BRAVO TERMINAL BLDG	G27	261	STL-4 TOOL CRIB
B6	217	BRAVO PRETEST BLDG	G27	262	STL-4 EQUIPMENT STORAGE
B34	218	COCA RECORDING CENTER	G28	263	STL-4 MODULE #2
B34	219	COCA TERMINAL BLDG	G21	264	MATERIALS TEST LAB OFFICE
B35	220	COCA FIRE HOUSE	G20	268	CRYOGENICS LAB
B34	222	COCA LOWER PRETEST BLDG	H8	269	CWLL LAB
B38	223	STORAGE	H2	270	ENGINEERING CHEM LAB
B24	224	PROPELLANT LOAD FACILITY	G13	271	CRYOGENIC TEST CELLS
B23	226	STORAGE	G27	274	CLEAN ROOM TRAILER
B6	233	PAINT STORAGE	G27	331	STL-4 INSTRUMENTATION WORKSHOP
B35	234	COCA UPPER PRETEST BLDG	H9	367	ECL CHEMICAL & SUPPLY ROOM
B35	235	COCA ELECT. CONTROL STATION-LOX	G34	389	STL-4 WORKSHOP
B34	236	COCA ELECT. CONTROL STATION-LH2	H15	418	COMPOUND A
B30	239	GH2 PUMPING STATION	B24	502	CONSERVATION AREA
B35	240	COCA HYDRAULIC PUMPHOUSE	G27	747	STL-4 CELL 24
B35	241	COCA FLAME DEFLECTOR PUMPHOUSE	G27	750	STORAGE
B35	451	COCA EQUIPMENT STORAGE	B25	784	CONSERVATION MACHINERY STORAGE
B4	507	ALFA/BRAVO FUEL FARM	G27	794	HOT WATER BOILER SHELTER
B23	508	COCA/DELTA FUEL FARM	H2	798	ECL DRUM & BOTTLE SHELTER
B35	509	AREA 2 SWITCH STATION	G27	945	STL-4 WIRE STORAGE
B27	515	SEWAGE TREATMENT PLANT	G28	973	STL-4 CELL 29
B40	519	STORABLE PROPELLANT AREA			
B26	679	COCA ENGINEERING TRAILER			
B17	711	SECURITY RADIO BLDG, SKYLINE			
B37	727	ALFA #1 TEST STAND			
B38	729	ALFA #3 TEST STAND			
B7	730	BRAVO #1 TEST STAND			
B7	731	BRAVO #2 TEST STAND			
B34	733	COCA #1 TEST STAND			
B38	739	STAND TALKER SHACK			
B26	760	MAINTENANCE SUPPLY SHELTER			
B40	761	SCALE SHELTER (SPA)			
B40	769	OXIDIZER STORAGE SHELTER			
B40	770	STORAGE PROPELLANT OFFICE			
B34	776	SEWER TREATMENT PLANT BLDG			
B40	777	OXIDIZER STORAGE SHELTER			
B35	787	COC/ #4 TEST STAND			
B19	796	PAINT SPRAY SHED			

IN

OUT OF RI Area 3

But Should Be Included